

Building Update

Howard High School Community
Tuesday, May 2, 2017

During the recent IEQ Audit completed on May 1, a suspicious growth, which may be mold, was found in the Wrestling Room on several pipe surfaces that go through the ceiling. The pipes are located directly above the doors to the room. The appropriate HCPSS personnel have been notified. An IEQ work order has been created. The room will not be used until the situation has been remediated. Thanks for your understanding.

I will keep you updated as necessary.

Nick Novak
Principal
Howard High School